

# EAST RENFREWSHIRE ACCESS PANEL

## ACCESS GUIDE AUDIT FORM



PREMISES: **Clarkston Hall** TYPE: **Community Letting Facilities**

ADDRESS: **Clarkston Road, Clarkston**

TELEPHONE NUMBER: **0141-638-4050**

### 1. PARKING FOR DISABLED DRIVERS/PASSENGERS:

1.1 Location: **Car park – front of hall and side of hall**

1.2 On street:  Off street:  Number of spaces:

1.3 Distance to entrance/access: **Approx. 20 (m)**

1.4 Accessible by Wheelchair: Yes  No

1.5 Additional comments: **Disabled parking bay x 5 bays near lift approx. 6 (m)**

### 2. ACCESSIBILITY: EXTERNAL:

2.1 Surface to entrance: Material **Tarmac**

2.2 Gradient: Level  Slight incline   
Moderate incline  Severe incline

2.3 Steps: Yes  No  Number  **19**

2.4 Ramp: Yes  No

2.5 Door(s): Automatic  Manual   
Double  Single   
Stiff/Heavy  Easy/Light

Width: **1240mm**

2.6 Handrails: Left  Right  None

2.7 Accessible by Wheelchair Yes  (via lift) No

2.8 Additional comments: **Steps at all emergency exits also internal stairs to committee rooms and staff area at back of the hall. New exit ramp at rear, but this leads to steps at side of building. Therefore, there is no wheelchair escape.**

3. ACCESSIBILITY: INTERNAL:

- 3.1 More than one floor/level: Yes  No
- 3.2 Lift: Yes  No
- 3.3 Ramp: Yes  No
- 3.4 Internal floor material: Carpet, vinyl, wood. Kitchen thermoplastic.
- 3.5 Evac+chairs available: Yes  No
- 3.6 Accessible by Wheelchair: Yes  No
- 3.7 Provision for Sensory Impairment:
- |          |     |                                     |    |                                     |
|----------|-----|-------------------------------------|----|-------------------------------------|
| Visual:  | Yes | <input checked="" type="checkbox"/> | No | <input type="checkbox"/>            |
| Hearing: | Yes | <input type="checkbox"/>            | No | <input checked="" type="checkbox"/> |
- 3.8 Guide Dogs Welcome: Yes  No
- 3.8 Can the service be brought to the customer: Yes  No
- 3.9 Additional comments: Loop system available from Eastwood House on request.

4. TOILETS:

- 4.1 Available to public: Yes  No
- 4.2 Ordinary toilet: Yes  No
- 4.3 Toilet for disabled: Yes  No
- 4.4 Accessible by Wheelchair: Yes  No
- 4.5 Door width: 840mm
- 4.6 Cubicle door width: 600mm
- 4.7 Provision for Sensory Impairment: Yes  No
- 4.6 Any other comments: Ladies and disabled toilet areas accessed through cloakroom. Door width 775mm. Toilet floor is quarry tiles.

5. FURTHER DETAILS:

- 5.1 Manager's office Yes  No
- 5.2 Opening hours: As required by lessee

Date of Audit : October 2006