

EAST RENFREWSHIRE ACCESS PANEL

ACCESS GUIDE AUDIT FORM

PREMISES: **TSB Clarkston**
ADDRESS: **18 Busby Road, Clarkston, G76 7XL**
TELEPHONE NUMBER: **0845-727-3333**



1. PARKING FOR DISABLED DRIVERS/PASSENGERS:

1.1 Location: no disabled spaces

1.2 On street: Off street:

1.3 Distance to entrance/access: depends on parking

1.4 Accessible by Wheelchair: Yes No

2. ACCESSIBILITY: EXTERNAL:

2.1 Surface to entrance:

2.2 Gradient: Level Slight incline

Moderate incline Severe incline

2.3 Steps: Yes No Number

2.4 Ramp: Yes No

2.5 Door(s): Automatic Manual

Double Single

Stiff/Heavy Easy/Light

Width

2.6 Handrails: Single Double None

2.7 Accessible by Wheelchair: Yes No

3. ACCESSIBILITY: INTERNAL:

- 3.1 More than one floor/level: Yes No
- 3.2 Lift: Yes No
- 3.3 Ramp: Yes No
- 3.4 Internal floor material: carpet
- 3.5 Evac+chairs available: Yes No
- 3.6 Accessible by Wheelchair: Yes No
- 3.7 Provision for Sensory Impairment:
- | | | | | | |
|----------|-----|-------------------------------------|----|--------------------------|----------------------------------|
| Visual: | Yes | <input checked="" type="checkbox"/> | No | <input type="checkbox"/> | Large print and Braille on order |
| Hearing: | Yes | <input checked="" type="checkbox"/> | No | <input type="checkbox"/> | |
| | Yes | <input checked="" type="checkbox"/> | No | <input type="checkbox"/> | |
- 3.8 Guide Dogs Welcome: Yes No
- 3.8 Can the service be brought to the customer: Yes No
- 3.9 Additional comments: arrangements can be made for home visits – staff very

helpfull

4. TOILETS: NONE

- 4.1 Available to public: Yes No
- 4.2 Ordinary toilet: Yes No
- 4.3 Toilet for disabled: Yes No
- 4.4 Accessible by Wheelchair: Yes No
- 4.5 Door width:
- 4.6 Cubicle door width:
- 4.7 Provision for Sensory Impairment: Yes No
- 4.6 Any other comments:

5. FURTHER DETAILS:

- 5.1 Manager's office: Yes No
- 5.2 opening hours: M & T – 9-30am to 4pm, W – 10am to 4pm, Th & F – 9-30am to 5pm

6. DATE OF AUDIT: August 2005