

EAST RENFREWSHIRE ACCESS PANEL

ACCESS GUIDE AUDIT FORM - abridged



PREMISES: **Ireland & Yuill** **TYPE:** Dentist

ADDRESS: 62 Busby Road, Clarkston, G76 7AT

TELEPHONE NUMBER: 0141-620-3131

1. **PARKING:**
There are off street parking spaces and the staff are very willing to help. Wheelchair accessibility is possible
2. **ACCESSIBILITY: EXTERNAL:**
The gravelly parking leads to a basic paved pathway. There are no steps and no incline to a stiff, single, manual door. There are no handrails but accessibility by wheelchair is possible.
3. **ACCESSIBILITY: INTERNAL:**
The internal floor is tiled and no upper floor. Guide dogs are welcome but no provision is made for sensory impairment. The service can be brought to the customers domicile if requested.
4. **TOILETS:**
An accessible toilet is available to the public which has been adapted for disabled use
5. **FURTHER DETAILS:**
See full audit for opening hours or go to <http://www.ireland-yuill.com>
6. **DATE OF AUDIT**
August, 2005